

File 1017-59

DPS-1017-59

2

6 February 1959

SUBJECT: Completion of Contract No. BC-450
through 30 June 1958

TO: Contracting Officer

Reference your letter DPS-5983 dated 3 December 1958 which requested acknowledgement of certain items of work performed under Contract No. BC-450. Please be advised that, as far as can be determined, the contractor has complied with the work directed by the following contract approval letters or the intent of these letters.

a. CH-0098 dated 9 May 1958: This letter covered a Product Improvement program in May and June 1958 on the "C" Configuration and was later included under Contract No. HF-32-27 with a Period of Performance beginning 23 May 1958.

b. 25434 dated 18 March 1958: Paragraph 2.(a) is chargeable to Customer No. 1. In performing work authorized under paragraph 2.(b), costs incurred will be shared equally by Customers No. 1 and No. 2. Paragraphs 2.(c) and 2.(d) apply only to Customer No. 1.

c. DPS-0288 dated 6 May 1958: The contractor has completed the overhaul and modification of four "B" Configurations as directed and delivered them to Customer No. 2.

d. DPS-0771/A dated 26 May 1958: This letter applies to Customer No. 1 only.



Lt. Colonel, USAF

25X1A

SECRET

25X1A

DISPATCH NO. [REDACTED] - -360
Page 1 of 1 page
Copy 1 of 4 copies

DATE: 6 April 1959

TO : Headquarters
FROM : Chief of Supply Depot
SUBJECT: Receiving Under Contract BC-450
REF: Dispatch No. [REDACTED] 786

1. (a) SAPC-17871 and (b) SAPC-18925. Two each 300" Collimators Serial Numbers 1 and 2 were repaired by Hycon under contract BC-450. Three (3) each 300" Collimators Serial Numbers 3,4, and 5 were returned to Perkins Elmer for repair under contract SC-21-54, Depot voucher No. 58-4417. Depot has no record as to type of work accomplished by either contractor.

2. (c) SAPC-25051. Depot has no record of "C" Power Cart being reworked. To further substantiate this, Depot contacted Mr. Hycon Spares Coordinator and he states Hycon has repaired one (1) "C" Power Cart serial No. 2. This "C" Power Cart is the property of [REDACTED] and was repaired against FOG W/O No. 3-25-36.

3. (d) DPD-1019-59. Four (4) each "B" Configuration serial Numbers 1, 3, 7, and 17 have been overhauled and modified and delivered to customer #2 as directed by DPS-0288, dated 6 May 1958. Depot has no record of type of work accomplished by the Contractor.

25X1A

25X1A

APR 8 3 00 PM '59

DOCUMENT NO. 51182
NO CHANGE IN CLASS. X
11 FEBRUARY
SEARCHED 11 SERIALIZED 11 INDEXED 11
FILED 11 SERIALIZED 11 INDEXED 11
SEARCHED 11 SERIALIZED 11 INDEXED 11
FILED 11 SERIALIZED 11 INDEXED 11
DATE 5/1/82 DELIVERED 004540 2013

~~SECRET~~

~~SECRET~~

DPD-5095-59

27 July 1959

MEMORANDUM FOR : Comptroller, DPD
SUBJECT : Receiving - Contract No. BC-450,
Hycon Mfg. Company

1. This is to advise that to the best of my knowledge
the Contractor has complied with the work directed by the
following contract approval authorizations or the intent of
these authorizations:

(a) Paragraph 2(b)(1) of Contracting Officer
letter dated 18 March 1958, SAPC-25434.

(b) [REDACTED] - OUT 90401 Headquarters
Approval No. 59-6.


25X1A

25X1A

[REDACTED]

Major, USAF

CL



18 August 1959

Reference: TWX IN1903 dated 24 July 1959

Dear Sir:

In answer to the referenced TWX we wish to submit the following information. The information is based on work orders that we have received from the Depot. All repair work that is performed in our M & O is covered by Depot work order and the reworked items are returned to the Depot against the work order numbers on which they were received.

We have matched the letters referenced in your TWX to Depot work orders.

In your item #2 we concur the 2 ea. 300" Collimators were repaired by us.

In your item #3 1 ea. Part #735420, "C" Power Cart, Serial #2 was received 4-9-58 on Customer No. 2 Work Order No. 3-25-31, Voucher #8023800. The unit was repaired and returned 10-28-58 on our Shipping Memo #79906.

25X1A

One (1) ea. Part #735420 "C" Power Cart was repaired and sent to the [REDACTED] for use by our Test Site personnel. It is now on test site inventory.

In your item #4 four (4) each Configuration B, Serial #1, 3, 7 and 16 were reworked and shipped to [REDACTED] Serial #1 and 16 on Work Order 5-12-38, Serial #3 and 7 on Work Order 4-25-35 shipped on 7-25-58, Shipping Memos 90597, 90598, 90599 and 90600.

25X1A

Three (3) each Configuration A-1, Serial #3, 5 and 8 were reworked on Vouchers No. 58-8390, 58-10442 and 58-5114 and were returned (Serial #3 and 5) on 10-30-58, Shipping Memo #79917 and (Serial #8) on 12-2-58, Shipping Memo #90613.

One (1) each Configuration A-2, Serial #8, was reworked on Voucher #58-5114 and returned 12-3-58 on Shipping Memo #90625.

In your item #5, One (1) each Configuration A-1 and one (1) Configuration A-2 were shipped to [REDACTED] on our Shipping Memos #90613 and 90625.

25X1A

If additional information is required please do not hesitate to call us.

Very truly yours,

HYCON MFG. COMPANY

[REDACTED] 25X1A

RGK/pe